

L Number	Hits	Search Text	DB	Time stamp
24	532	280/495	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 22:43
27	5	280/495 and "dc"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 22:47
28	6	("3431005"   "4072257"   "4438945"   "5219105"   "5458389"   "5593139").PN.	USPAT	2002/06/30 22:44
29	4	5707072.URPN.	USPAT	2002/06/30 22:45
30	1	280/495 and "ac"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 22:51
31	11	("3843165"   "4893856"   "5277448"   "5507515"   "5511813"   "5609004"   "5628536"   "5845948"   "6095546"   "6173984"   "6234512").PN.	USPAT	2002/06/30 22:48
32	12	("D349083"   "2342907"   "3271050"   "3782761"   "4040641"   "4509770"   "4738464"   "4852902"   "5094469"   "5560631"   "5628536"   "5775560").PN.	USPAT	2002/06/30 22:49
33	1	6095546.URPN.	USPAT	2002/06/30 22:50
34	272	hitch and "dc"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 22:52
35	125	(hitch and "dc") and trailer	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 23:00
36	69	(hitch and "dc") and (outlet or receptacle)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 23:14
37	9	("3159368"   "3718317"   "3900214"   "3989266"   "4127295"   "4202562"   "4331323"   "4381069"   "4746137").PN.	USPAT	2002/06/30 23:08
38	13	5072962.URPN.	USPAT	2002/06/30 23:09
39	4	("2942456"   "3448228"   "3784773"   "3794786").PN.	USPAT	2002/06/30 23:12
40	1	2002-097053.NRAN.	DERWENT	2002/06/30 23:13
41	0	20010050471.URPN.	USPAT	2002/06/30 23:13
42	1026	hitch and trailer and (outlet or receptacle)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 00:04
43	502	(hitch and trailer and (outlet or receptacle)) and power	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 23:15
44	53	((hitch and trailer and (outlet or receptacle)) and power) and ("ac" or "dc")	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/06/30 23:15
45	15	("D335122"   "4248494"   "4261634"   "4270115"   "4405190"   "4726786"   "4781393"   "4846697"   "4936796"   "5127844"   "5281147"   "5354204"   "5443389"   "5514009"   "5626479").PN.	USPAT	2002/06/30 23:31
46	9	("2660679"   "3092430"   "4057310"   "4072381"   "4182005"   "4270115"   "4405190"   "4477801"   "4648682").PN.	USPAT	2002/06/30 23:17
47	17	("0774611"   "2070832"   "2581994"   "2660679"   "2797337"   "2975297"   "2989645"   "2994001"   "3004170"   "3417213"   "3466453"   "3494657"   "3497707"   "3915476"   "3957333"   "4005313"   "4057310").PN.	USPAT	2002/06/30 23:20

49	15	3497707.URPN.	USPAT	2002/06/30 23:21
50	11	("D223082"   "D324990"   "0950361"   "1068391"   "2436533"   "2730183"   "3127114"   "3307710"   "3497707"   "3915476"   "4883433").PN.	USPAT	2002/06/30 23:22
51	11	5288094.URPN.	USPAT	2002/06/30 23:23
52	4	("4772220"   "4940427"   "5288094"   "5380209").PN.	USPAT	2002/06/30 23:25
53	1	6089907.URPN.	USPAT	2002/06/30 23:25
54	9	("3400293"   "3817558"   "5066034"   "5082217"   "5306037"   "5765851"   "5915715"   "5957475"   "6089907").PN.	USPAT	2002/06/30 23:26
56	7	3400293.URPN.	USPAT	2002/06/30 23:27
57	10	("3577115"   "3613044"   "3782761"   "4738641"   "4772220"   "4800471"   "5288094"   "5407219"   "5603178"   "5800188").PN.	USPAT	2002/06/30 23:30
58	16	("2705157"   "3059105"   "3080581"   "3331957"   "3381118"   "3691366"   "3885146"   "4091442"   "4195704"   "4449167"   "4463411"   "4602320"   "4613927"   "4626967"   "4692845"   "4703398").PN.	USPAT	2002/06/30 23:31
59	17	4800471.URPN.	USPAT	2002/06/30 23:32
60	14	("D254846"   "D273778"   "D332942"   "D345145"   "D358370"   "2643787"   "2878301"   "4747506"   "4781393"   "4842524"   "5288094"   "5407088"   "5407219"   "5443389").PN.	USPAT	2002/06/30 23:37
61	1	5904261.URPN.	USPAT	2002/06/30 23:38
62	14	"5288094"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 00:05
63	5	"5904261"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:19
64	3	"6305945"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:47
65	1	6305945.URPN.	USPAT	2002/07/01 01:21
66	1	2002-024741.NRAN.	DERWENT	2002/07/01 01:21
67	2	280/\$.ccls. and trialer and hitch and battery	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:48
68	0	439/\$.ccls. and trialer and hitch and battery	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:49
69	0	220/\$.ccls. and trialer and hitch and battery	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:49
70	2	trialer and hitch and battery	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:49
71	860	hitch and battery	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:49
72	17	(hitch and battery) and inverter	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/07/01 01:56
73	6	("3505742"   "3286357"   "3111907"   "0842379"   "0670594"   "0874373").PN.	USPAT	2002/07/01 01:56

74	58	(hitch and battery) and "ac"	USPAT; EPO; JPO; DERWENT; IBM_TDB USPAT	2002/07/01 02:06
75	15	("D335122"   "4248494"   "4261634"   "4270115"   "4405190"   "4726786"   "4781393"   "4846697"   "4936796"   "5127844"   "5281147"   "5354204"   "5443389"   "5514009"   "5626479").PN.	USPAT	2002/07/01 01:59
76	15	("D335122"   "4248494"   "4261634"   "4270115"   "4405190"   "4726786"   "4781393"   "4846697"   "4936796"   "5127844"   "5281147"   "5354204"   "5443389"   "5514009"   "5626479").PN.	USPAT	2002/07/01 02:00
77	10	5766020.URPN.	USPAT	2002/07/01 02:00
78	675	vehicle and battery and hitch	USPAT; EPO; JPO; DERWENT; IBM_TDB USPAT	2002/07/01 02:06
79	59	(vehicle and battery and hitch) and converter	USPAT; EPO; JPO; DERWENT; IBM_TDB USPAT	2002/07/01 02:07
80	10	("0786376"   "1207658"   "1790634"   "3190387"   "3454122"   "3477537"   "3497027"   "3621929"   "3690397"   "3837419").PN.	USPAT	2002/07/01 02:17